



## Sub Inspection Report

### Smoke Detector

Acme Alarm Company  
 3221 East Street  
 Springfield, IL 62711  
 Phone: (217) 787-1133  
 Fax: (217) 787-1171

Activity Date: 1/18/2008 12:00:00AM  
 Activity Number: I-BL-08-0001.S0005  
 Activity Cause: Periodic  
 Inspector Name: Bob Lee  
 Inspector Phone: 217-787-1133  
 Status: Fail

### Inspected Party

Risky Business  
 (AAC2)  
 2333 Broadway Street Basement  
 Springfield, IL 62711  
 (217) 787-1133

Occupancy Type:  
 Property Use:  
 Total Deficiencies 1  
 Total Fees \$7.00  
 Hrs: 0.25

<u>Item Type</u>	<u>Description</u>	<u>Location</u>	<u>Item Number</u>	<u>Bar Code</u>	<u>Cost</u>	<u>In Service Date</u>	<u>Status</u>
Smoke Detector	SD 05	Basement North	Z2, 05	002357		01/18/2008	In Service

## Smoke Detector

2. Smoke Detector device passed functional test  
*Fail*  
*needs to be replaced*

## Deficiencies

1 Ref. Number: NFPA 72 (2007) 10.6.2.3\* Maintenance, Inspection, and Testing Records.  
 A record of all inspections, testing, and maintenance shall be provided that includes the following information regarding tests and all the applicable information requested in Figure 10.6.2.3: (1) Date (2) Test frequency (3) Name of property (4) Address (5) Name of person performing inspection, maintenance, tests, or combination thereof, and affiliation, business address, and telephone number (6) Name, address, and representative of approving agency(ies) (7) Designation of the detector(s) tested, for example, "Tests performed in accordance with Section \_\_\_\_\_." (8) Functional test of detectors (9) Functional test of required sequence of operations (10) Check of all smoke detectors (11) Loop resistance for all fixed-temperature, line-type heat detectors (12) Other tests as required by the equipment manufacturer's published instructions (13) Other tests as required by the authority having jurisdiction (14) Signatures of tester and approved authority representative (15) Disposition of problems identified during test (e.g., owner notified, problem corrected/successfully retested, device abandoned in place)

## Fees

Smoke Detector \$7.00

Comments:

**Inspected Party**

Risky Business

(AAC2)

2333 Broadway Street Basement

Springfield, IL 62711

(217) 787-1133

Occupancy Type:

Property Use:

Total Deficiencies 1

Total Fees \$7.00

Hrs: 0.25